

FIRE SAFETY



Corrosion of fire damper



Hold-back wire attached to fire door



Corrosion of fire door and door frame



Leakage of fire line



**Malfunction of fire line
isolation valve due to mud**



**Corrosion and
leakage of
main fire pump**



**EEBD covered by
flammable
material (vinyl)**



Damage to insulation material for fire line suction pipe (passing through engine room)



Improper stowage of flammable material in accommodation

LIFE SAVING APPLIANCES



Lifeboat safety belt partly missing



Inoperative lifeboat hook




**Deterioration of lifeboat drain plug
(rubber ball)**



**Holes on lifeboat embarkation
station platform**



Usage of unapproved life raft hook



**Improper connection of
hydrostatic release unit (HRU)**

LOAD LINE / SAFETY CONSTRUCTION



Hatch cover packing partly missing



Corrosion of hatch coaming



Access hatch closing bolt partly missing



Corrosion of natural ventilator



Corrosion of air pipe head



Defective air pipe head fittings



Corrosion of hatch cover cleat



**Incorrect marking of
ventilation open/close direction**



Damage to upper deck handrail

ENGINE ROOM (SOLAS)



**Insufficient diesel for
emergency generator**



**Leakage and
accumulation
of main
engine oil**



**Malfunction of engine console
in engine control room**


ENGINE ROOM / MARPOOL



**Corrosion and
damage of
sewage
treatment plant**



**Damage
to incinerator
furnace refractory
material**



**Inappropriate
management/
storage of
garbage**

OTHERS



Modification of fire division without approval



Modification of accommodation compartment without approval



Modification of electrical equipment and penetration without approval



Damage to upper deck access means



**Corrosion and holes in upper
deck bulwark stay**



Disorder in Bos'n Store