

PSC OBSERVATIONS OF THE WEEK

WK - 26

ENGINE ROOM



FIRE SAFETY



LIFE SAVING APPLIANCES



LOAD LINE

SAFETY
CONSTRUCTION



**MARINER'S
UPDATE**

COMPLIANCE WITH SIMPLICITY



**PSC
INSPECTOR**

FIRE SAFETY



Dismantled fire detector



Hold-back wire attached to a fire door



Broken hydrant handle



**Leakage from
fire line**



**Corroded/holed
fire damper
for E/R**




**A fire door prevented from
closing by cabinets**

LIFE SAVING APPLIANCES



Peeling paint on lifebuoy



**Improper reset of lifeboat
release mechanism**



Damaged hydrostatic release unit

LOAD LINE



**Broken float/worn out rubber packing
of the air pipe head**



Missing sounding cap



Damaged guard rail

LOAD LINE / SAFETY CONSTRUCTION



Unacceptable gaps in hatch covers



**Corrosion/crack
on hatch
coaming stay**



**Damaged cleat
for hatch cover**

ENGINE ROOM (FIRE SAFETY)



**Dirty condition due to oil leakage
and accumulation**



**Dirty condition due to oil leakage
and accumulation**



**Deterioration/peeling of insulation on
exhaust pipe of M/E**

ENGINE ROOM / MARPOL



Defective pressure gauge of FO pump



**Leaking
from
pipeline of
sewage
treatment
plant**



**Inappropriate
management
/storage
of garbage**

OTHERS



Oil leakage from hydraulic piston for hatch cover



**Unreported temporary repair
with cement box to RO**



**Corroded/holed platform of
accommodation ladder**