

PSC

OBSERVATION OF THE WEEK

(PSC FOCUS - WK : 31)



FIRE SAFETY



Leakage from fire line



Disconnected pilot line for fixed CO2 fire extinguishing system

FIRE SAFETY



Detached insulation on underside of deck



Improper cable penetration (through fire door frame)

FIRE SAFETY



Hold-back hook fitted on self-closing door



Emergency shut-off valve not ready for use (secured by wire)

FIRE SAFETY



Wasted fire damper flap



Holes on ventilation trunk and No marking of "Open-Shut" positions

LIFE SAVING APPLIANCES



Poor condition of embarkation ladder



Improper reset of on load release gear interlock lever

LIFE SAVING APPLIANCES



Deteriorated reflective tape



Fractures on lifeboat hull

LOAD LINE



Wasted gooseneck ventilator



Hole on air pipe head

LOAD LINE



Missing of hatchway securing device



Wasted and corroded hatch cover securing device

MARPOL / MACHINERY SPACE



Clogged oil water separator



Oily and dirty engine room

MARPOL / MACHINERY SPACE



Oil leakage and accumulation



Pipe temporarily repaired with rubber patch

OTHERS



Corrosion holes on strength deck



Crack at toe of hatch side coaming end bracket

OTHERS



Worn link and missing of stud



Deteriorated mooring line