


PSC OBSERVATION OF THE WEEK

PSC FOCUS - WK : 33



Photographs of Deficiencies identified during Port State Control



Inadequate re-setting of on-load release gear



Leaked fire line



Disconnected CO2 bottle



Oily and dirty E/R floor



Patched sea water pipe



Missing butterfly nut

Wasted gooseneck air vent



Starboard side fuel oil tank vent pipe corroded/ broken.





Defective air pipe.



Fire main pipe leaking during testing



Serious corrosion of the vessel.



Deteriorated vinyl floor tiles

OTHERS



Oily, unnecessary items scattered engine room



Damaged corrosion of Bulwarks and Freeing port



Open / Not secured electrical wires hazard