





PSC FOCUS WK - 34

PSC OBSERVATIONS OF THE WEEK



Photographs of Deficiencies identified during Port State Control



**Incorrectly mounted HRU on an inflatable liferaft.
The painter should be attached to the HRU**



Wasted engine room fire damper



Sanitary facilities not fit for use



Main deck holed found masked with tape painted in red



Leaking auxiliary engine



Illegal pipe - sludge pump to overboard

3 medical first aid kits for deck, engine and catering departments are not available.



Pilot ladder is not complying with requirements





Rescue boat on boat-deck starboard side found hole on bottom.



Inflatable liferafts not working properly - interval of serviced date exceed 12 months



Pipe of fixed fire-extinguishing system (CO₂) for cargo hold cut and heavily corroded.



Quantity of food not suitable for the intended voyage



Sanitary facilities unhygienic; equipment are missing and not functioning; washing machine in laundry room missing.



Fire detection alarm system not working.