



PSC FOCUS WK – 35


PSC OBSERVATIONS

— OF THE WEEK —



MARINER'S UPDATE
COMPLIANCE WITH SIMPLICITY

Photographs of Deficiencies identified during Port State Control



Significant corrosion and wastage on gooseneck vent.



**Malfunctioning smoke detector, wrapped in plastic to prevent
recurring alarm sounding**



Blocked fuel valve preventing remote actuation



Improperly secured and labeled escape door



Oil on discharge side of oily-water separator



Bad condition of mooring rope.

LIFEBOATS (P.S., STB.S.) - SCATES ARE MISSING




LAUNCHING INSTRUCTIONS FOR LIFEBOAT ARE UNREADABLE





LIFEBOAT (P.S.) - RUDDER IS CORRODED AND HAS HOLES DUE TO CORROSION



SECURING DEVICES FOR LASHINGS OF LIFEBOATS (P.S.), (STB.S.) ARE HEAVILY CORRODED



STOWAGE OF LIFERAFT (P.S.) - WEAK LINK IS MISSING



LIFEJACKETS FOR LIFERAFT ON FORECASTLE ARE IN POOR CONDITION



**CLOSING DEVICES FOR THE DOOR OF CARGO HOLD
VENTILATION ROOM ARE MISSING**



**UNSAFE STOWAGE OF THE GANGWAY
LADDER WHICH WOULD ENDANGER THE
SAFE ACCESS TO THE VESSEL.**

OTHERS

