

— PSC FOCUS —

WK : 32



PSC OBSERVATION OF THE WEEK



**PSC
INSPECTOR**

**PSC
INSPECTOR**

LIFE SAVING



Corrosion and Hole of water spray



Improper reset of on load release gear interlock lever



Seize of on-load release gear by excessive paint




Poor condition of lifeboat hull

FIRE SAFETY

Holed fire line



Dis-connected pilot line for CO2 discharge valve



Poor condition of firemens' outfits



MARPOL

Illegal repair by patch with putty of Oily Water Separator



MACHINERY SPACE



Oily and dirty engine room



Oily lagging of F.O. piping

LOAD LINE



Detached gasket of cargo hold air vent




Holed funnel ventilation

OTHERS



Corrosion holes of strength deck



Wasted mooring line