



PSC FOCUS – WK : 27



PSC OBSERVATION — of the — WEEK

**FOCUS. CORRECT.
PREVENT.**



**COMMON DEFICIENCIES.
REAL IMPACT.
SAFER SHIPPING.**

SOLAS (FIRE SAFETY)



Cylinder hose disconnected (Fixed CO2 extinguisher system)



Inappropriate temporary repair & leakage from fire line



Fault alarm on smoke detection alarm panel



Hold-back hook attached to a fire door that is required to be self-closing



**Missing non-combustible
compounds**



Wasted / damaged fire door gasket

SOLAS (LIFE SAVING APPLIANCES)



Damaged life buoy




**Corrosion holes on
accommodation ladder**



Damage to equipment inside the lifeboat

SOLAS (SAFETY NAVIGATION)



Air bubble in the magnetic compass



Missing wiper for the bridge window

SOLAS (SAFETY CONSTRUCTION)




Cracks on hatch coaming & its bracket


LOAD LINE / SAFETY CONSTRUCTION



Broken float disc of the air pipe head



**Deformed / cracked stanchion for
guard rails & chains disengaged**



Corrosion hole on the ventilation hatch coaming

MACHINERY SPACE



Leakage from pipeline




Dirty condition with oil



Excessive oily bilge on the E/R bottom

MARPOL



Drain plug missing



Leakage from the on board hydraulic system

OTHERS



Unusable toilet