



PSC FOCUS

WK : 28



PSC

OBSERVATION OF THE WEEK



MARINER'S UPDATE


COMPLIANCE WITH SIMPLICITY



SOLAS (FIRE SAFETY)



Fire hazard due to oil leakage in engine room




Fire door packing deteriorated and detached



Leakage from fire main



Broken fire door frame




**Elec. cables penetration
compound missing**




Heavy corrosion on CO2 pipes

SOLAS (LIFE SAVING APPLIANCES)



**Broken instruction plate for
inflatable liferaft**



**Inappropriate reset of on-load
release gear**



Inappropriate painter securing



Deteriorated grab line of lifebuoy


LOAD LINE



Broken float disc of air pipe head



Improper freeboard marks



Wasted ventilator

MACHINERY SPACE



Temporary repair on piping without reporting to PSC



Dirty condition in engine room




Dirty condition in engine room

MARPOL



Dirty condition in oily bilge water discharge line



Wasted and holed on sewage treatment plant

OTHERS



Partly broken mooring rope



Missing toilet