

PSC FOCUS WK : 29

PSC OBSERVATION OF THE WEEK



FIRE SAFETY




Deteriorated insulation



Missing compound



Missing doorknob




Missing fire door packing




Heavy leakage from fire hydrant



Heavy leakage from fire hose



Inappropriate adjustment of damper




Heavy corrosion/hole on CO2 line

LIFE SAVING APPLIANCES



Broken mask



Inappropriate reset of on-load release gear




Inappropriate painter securing




Deteriorated grab line

LOAD LINE




Missing rubber seat for air pipe head



Improper LL marks



Holed ventilator



Missing butterfly nut

MACHINERY SPACE




Dirty pressure gauge



Oil leakage

MARPOL



Holed oil coaming



A huge amount of garbage


OTHERS



Partly broken mooring rope



Missing toilet



Broken wire drum



Broken fairleader